

## Positive Responses for Standard Dig Notice Tickets effective 9/1/2018

- 000 RESPONSE PENDING- System generated default response attached to initial request
- 001 NO CONFLICT- Facility is outside of stated area/scope of excavation
- 002 MARKED- Facilities have been marked
- 003 NOT COMPLETE- None or some of the facilities have been marked, more time needed, coordination or assistance required to complete locating of facility
- 004 MARKED-UTILITY REQUIRED ON SITE DURING EXCAVATION- Facility owner operator required to be on site when excavating within noted scope of work for this specific facility
- 005 ON GOING COORDINATION- On-going mutual cooperation between facility owner operator and excavator
- 006 NOT MARKED-NO ACCESS TO WORK AREA-Facility owner operator could not get access to work area, and requires coordination with excavator
- 007 STATED SCOPE OF WORK COMPLETE- Facility owner operator confirmed stated scope of work found completed prior to dig start date
- 008 FACILITY RESPONSE NOT REQUIRED- For RXMT locate requests only (retransmitted at the excavator's request) and intended for specific facility or facilities that have NOT been requested to locate. Example- the RXMT locate request states "Locate Gas and Electric only". In this case, all other facility owners (water, sewer, telephone, cable TV, etc.) would respond with "FACILITY RESPONSE NOT REQUIRED". Facilities that were requested (Gas and Electric) would choose from one of the other possible valid positive responses
- 009 ADDITIONAL LOCATING REQUIRED- Facility owner discovered field conditions require additional locating and will communicate with excavator on resolution of additional locating issues
- 010 EXEMPT FROM MARKING- As defined in Public Act 174 Section 460.727 Sec. 7 (9). This is a system generated response
- 011 NOT MARKED-EXCAVATOR CONTACTED FOR ADDITIONAL INFORMATION-Facility owner operator reached out to the excavator as noted on the locate request and requires additional information to properly complete locate request. Excavator required to contact facility owner/operator.
- 012 POSSIBLE ABANDONED FACILITY- There may be an abandoned facility in the proposed excavation area.
- 013 CANCELED- System generated response indicating the dig notice was canceled
- 014 REPORTED EXCAVATING WITH NO VISIBLE MARKS-This ticket was placed by a concerned citizen to alert facility owner/operators of possible excavation near the ticket location. This is a system generated response
- 999 HAS NOT RESPONDED- System generated response indicating the facility owner operator has not responded to the request



GREEN- Dig with caution following PA174 requirements

YELLOW- Contact facility owner operator; then dig with caution following PA174 requirements

RED- Do not Dig

## Positive Responses for *Design Ticket*Requests are not color coded as they are not Dig Notices

201 DESIGN-NO FACILITIES- No Facilities in area as described in the scope of excavation 202 DESIGN-TASK COMPLETED- Facility owner operator sent record drawings to designer 203 DESIGN-MARKING REQUIRED- As defined in Public Act 174 Section 6a paragraph (3)

(3) The response to a design ticket is to provide general information regarding the location of underground facilities, not to mark any facilities. However, if a facility owner or operator does not have drawings or records that show the location of a facility, the facility owner or operator shall mark that facility under the procedures described in section 7. A design ticket or information provided in response to a design ticket does not satisfy the requirement under this act for excavation or blasting notice to the notification system or marking the approximate location of facilities for blasting or excavation.

## **NOTES:**

Amended 11/16/15 for addition of code 011; 7/20/15 to clarify use of codes 007 & 008; 4/27/15 for addition of code 010; 8/11/18 for addition of code 014

