



POSITIVE RESPONSE CODES

Positive Response Codes Based on Ticket Type & Status

The Pelican system requires use of comments with every Positive Response code.

Normal 21-Day, Project 21-Day, Normal 180-Day, Project 180-Day, Short Notice, Emergency, Unmarked Facilities, Additional Assistance, and Destroyed Markings	
001 – NO CONFLICT	Dig with caution following PA 174 requirements: Facility is outside of stated area/scope of excavation.
002 – MARKED	Dig with caution following PA 174 requirements: Facilities have been marked.
003 – NOT COMPLETE	Do NOT dig: Locating was not completed because more time is needed; coordination or assistance required to complete the locating of the facility.
004 – MARKED, UTILITY REQUIRED ON-SITE DURING EXCAVATION	Dig with caution following PA 174 requirements: Facility owner/operator required to be on-site when excavating within noted scope of work for this specific facility.

Design <i>(Positive Response by member not required)</i>	
201 – NO FACILITIES IN MAPPED POLYGON	No facilities in mapped polygon
202 – TASK COMPLETED	Facility owner/operator sent record drawings to design
203 – MARKING REQUIRED	As designed in PA 174 Section 6a paragraph (3)



Auto-Response Codes

Auto-Responses (System-Generated): Design	
204 – DESIGNING NEAR AN MDOT RIGHT-OF-WAY	Please review the right-of-way maps at https://mdotjboss.state.mi.us/BITMIX/rowMapFilesHome.htm . If the project encroaches onto MDOT property, please contact the appropriate Transportation Service Center (TSC) for information regarding MDOT infrastructure. A map and list of TSC contacts is located at https://www.michigan.gov/documents/mdot/Permit_Contacts_by_Office_661871_7.pdf .

Auto-Responses (System-Generated): Normal 21-Day, Project 21-Day, Normal 180-Day, Project 180-Day, Short Notice, Emergency, Unmarked Facilities, Additional Assistance, and Destroyed Markings	
000 – RESPONSE PENDING	Do not dig: Legal start date and time has not started. This is a system-generated response.
010 – EXEMPT FROM MARKING	Dig with caution following PA 174 requirements: As defined in PA 174 Section 460.727 Sec. 7 (9). This is a system-generated response.
011 – THERE ARE NO MEMBERS IN THE SUPPLIED WORK AREA	Dig with caution following PA 174 requirements: There are no member facility owner/operators that request to be notified in the area of excavation. Your request has been forwarded to MISS DIG 811 managements for review. This is a system-generated response.
012 – POSSIBLE ABANDONED FACILITY	Dig with caution following PA 174 requirements: There may be an abandoned facility in the proposed excavation area. This is a system-generated response.
013 – CANCELED TICKET	Do not dig: The dig notice was canceled. This is a system-generated response.
020 – WORKING NEAR AN MDOT RIGHT-OF-WAY	Dig with caution following PA 174 requirements: Please review the right-of-way maps at https://mdotjboss.state.mi.us/BITMIX/rowMapFilesHome.htm . If the project encroaches onto MDOT property, please contact the appropriate Transportation Service Center (TSC) for information regarding MDOT infrastructure. A map and list of TSC contacts is located at https://www.michigan.gov/documents/mdot/Permit_Contacts_by_Office_661871_7.pdf .
999 – HAS NOT RESPONDED	Do not dig: Facility owner/operator did not provide a response by the response due date and time. Retransmit ticket for unmarked facilities. This is a system-generated response.



Additional Response Information

Private Locator Responses	
301 – CONTACTED REQUESTOR	No locate performed
302 – CONTACTED REQUESTOR	Locate performed

Excavator Positive Response Check
Excavators required to check off a box on Positive Response page before placing a RXMT to confirm they checked before beginning per PA 174